

HealtheCar VEHICLE ELECTRONIC CONDITION ANALYSIS

HealtheCar ID: VS573_CPO_05302013_143021_ENH;1 (For Retrieving HealtheCar From Database)

Test Information

Test Location	Auto E-Diag Service
Phone	(512)921-5685
Email	support@vhealth.biz
Date	19-NOV-2015
Time	13:38:41.320

Vehicle Information

Maker	Hyundai
Model	Santa Fe V6 2.7L
Year	2006
Mileage	129966
VIN	KM8SC73D16U101049

HealtheCar Score Summary

TEST RESULTS RANGE
1(POOR)-100(PERFECT)

TEST FINDINGS

73

VECRCheck Certified (Yellow): SOME MONITORED SYSTEMS INDICATE POSSIBLE PROBLEMS. SOME DTC CODES COULD INDICATE OPERATOR ERRORS. CURRENT DTC CODES --> Generic Powertrain: P0700 Transmission Control System (MIL Request) | Enhanced Powertrain: P0700 Transmission Control System (MIL Request) | SRS-Airbag: B1448 Passenger OC MAT Defect Error >(B1448 | P0700)> (Battery Voltage= 13.91 volts) (Time To Generate Report= 0:10:06) (Health Score= 73%) (B1448 | P0700)

<input type="checkbox"/>	If the following systems were repaired, the Health Score would be:	100
1	Generic Powertrain	
2	Enhanced Powertrain	
3	SRS-Airbag	

Overall Health Score

73

Number of Diagnostic Trouble Codes Reported

3

OVERALL TEST RESULT



Engine Health Score

85

Catalytic Converter

100

Anti-Lock Brake System



EGR Health Score

N/A

O2 Health Score

100

Transmission System



EVAP Health Score

100

Misfire Health Score

N/A

Air-Bag System



vHealth's Vehicle Electronic Condition Report System (VECR) provides a highly detailed health report that includes an indication of degradation of the vehicle's major systems and subsystems. Our proprietary analysis provides an accurate indication of the current condition of the vehicle's systems and likely near term failures.

Based on our scoring for this vehicle, this vehicle ranks in the top 27% of vehicles for a vHealth score in its model year.

REPORT LEGEND Green appropriate range Yellow may require attention Red required action needed